






Step 1



Step 2



Step 4



Step 3

Please refer to page 3 for wiring instructions.

COBRA Cure FX1

Configuration 2


Quick Start Manual



Step 1




Step 2



Step 3



Step 4



Step 7



Step 6



Step 5

COBRA Cure FX1
Configuration 3



Step 1



Step 2



Step 3



Step 4




Step 5



Step 6

Electrical



Safety

Warning: This product is a high power UV source classed in the Risk Group 3 as per IEC62471.

Risk Group 3 – High Risk. May pose a hazard even for momentary or brief exposure. Avoid eye and skin exposure to unshielded product.

Warning: DO NOT LOOK DIRECTLY AT THE UV LIGHT SOURCE. ALWAYS WEAR GOGGLES WHEN USING THIS PRODUCT.

Ensure the machine cannot operate without protective shielding in place.

Label Description



Symbol	Description
	Obey all safety messages that follow this symbol to avoid possible injury or death
	Warning indicates a potentially hazardous situation, which, if not avoided, could result in death or serious injury
	Wear protective gloves and use appropriate shielding
	Wear approved ultraviolet resistant eyewear and use appropriate shielding
	ULTRAVIOLET LIGHT hazard
	Hot surface hazard
	Must not be disposed of in the trash

